

## CT Cabinet Mounting Racks


*Stud & Lug Type*




**K4797 (studs)**




**K4798 (studs)**



**K5932 (studs)**




**K5933 (studs)**




**K4729 (with lugs)**



**K4722 (with lugs)**



**K5930 (with lugs)**



**K5931 (with lugs)**

### Hinge Cover Transformer Cabinets

Code	Catalog Number	AIC Rating	Amps	Volts	Type of Service	Termination Type
A	<b>K4797</b>	50K	800	600	1Ø3W or 3Ø3W	½ - 13 studs on 1¼" centers
B	<b>K4798</b>	50K	800	600	3Ø4W	½ - 13 studs on 1¼" centers
G	<b>K4729</b>	50K	800	600	1Ø3W or 3Ø3W	6 lugs: (3) #4-600 or (6) #1-250
H	<b>K4722</b>	50K	800	600	3Ø4W	8 lugs: (3) #4-600 or (6) #1-250
H	<b>K5930</b>	50K	800	600	3Ø4W	8 lugs: (3) #4-600 or (6) #1-250
G	<b>K5931</b>	50K	800	600	1Ø3W or 3Ø3W	6 lugs: (3) #4-600 or (6) #1-250
A	<b>K5932</b>	50K	400	600	1Ø3W or 3Ø3W	½ - 13 studs on 1¼" centers
B	<b>K5933</b>	50K	400	600	3Ø4W	½ - 13 studs on 1¼" centers

### Notes

- Select CT enclosures from previous page.
- **PT Cabinets:** PT Cabinets are required on all 277/480V installations.

